

Release Notes DIVUS CTP04 **1.2**

Date: 17/03/2025

Contents

1	DIVUS CTP04 1.2 operating system.....	2
2	DIVUS VISION 0.22.....	2
3	DIVUS CTP04 LAUNCHER 1.0 rev. 74.....	3
4	DIVUS VIDEOPHONE 4.6 r389.....	3
5	TeamViewer UniversalAddon 1551393.....	4
6	TeamViewer QS 15.61.634 - 1561634	4

1 DIVUS CTP04 1.2 operating system

Improvements

#4306: introduced EULA for support VPN access
Minor improvements

Bugfixes

#4502: Connection to KNX IQ fails if clocks are out of sync

2 DIVUS VISION 0.22

New Features

#1262: Function to copy or move elements into selected room
#1549: New concept of levels/rooms and tree view based navigation
#2031: New AC Element
#2723: New datapoint (Virtual driver)
#3061: New Energy management plugin
#4216: Remote access to KNX bus

Improvements

#4486: Increased total element limit to max. 500
#4469: Increased limit for thermostat logic elements to max. 50
#4425: Increased number of supported DIVUS device clients to max. 50
#3892: Re-order thermostat/thermostat logic parameters
#4572: New element/room selection for faster configuration
#4185: New switch control in elements function datapoint selection in ETS MODE
#4299: Hide thermostat/thermostat logic parameters instead of showing greyed out
#4328: Improve security checks when updating panel through VISION
#4372: Improve UI event handling performance
#4424: Copy also functions' linking when copying element
#4444: New room/level background colour palette
#4487: Improved wording in project reset prompt for ITALIAN language

Bugs

#3871: Fixed DTP 16 ISO 8859-1 support
#3893: Setpoint offset value interpreter for float values in thermostat element
#4275: Datapoints are not handled correctly in ETS MODE when deleting whole elements, resetting an element function to KNX GROUP OBJECT or linking a NON-KNX datapoint to a function
#4323: Host resolution improved to be case-insensitive

- #4324: Camera view does not appear when aborting and then restarting QR code scan in pairing procedure
- #4331: Local connection does not always use correct lookup protocol
- #4332: Text layout broken in single room selection popup
- #4343: Selected elements in rules configuration show the parent room name also in single room mode
- #4348: Time schedule validity range is not saved correctly when set before adding tasks in a new schedule
- #4390: User rights not purged correctly from element's permission override when user is deleted
- #4394: App crash when performing selection of text in search bar on SAMSUNG Galaxy tablets
- #4409: Wrong connection status icon after ETS download (local instead of cloud)
- #4420: Measured temperature font size not consistent on thermostat / thermostat logic element
- #4426: Missing name of the paired client device in "pairing successful" popup
- #4485: Element/Room permission changes are lost when navigating back to previous preferences page without saving
- #4547: Pairing input via numeric keypad no longer works after timeout

Minor fixes

3 DIVUS CTP04 LAUNCHER 1.0 rev. 74

Bugfixes

- #4053: CTP04 activation of the automatic restart causes reboots of the device even out of time

Improvements

- #4117: Remove power off option from CTP04 Launcher settings menu
- #4181: App wizard detailed DIVUS VISION App switch button design and optional normal design selection (VISION standard face can be disabled)
- #4118: Show IP address and MAC address on launcher info page

4 DIVUS VIDEOPHONE 4.6 r389

Features

- #4368: added new Commend (manuf.) intercom template

Bugfixes

- #4474: fixed door call through digital input not triggered while not registered

4546: fixed some JPEG streams not opening

5 TeamViewer UniversalAddon 1551393

#4520: updated to currently newest available version (January 2025)

6 TeamViewer QS 15.61.634 - 1561634

#4520: updated to newest available version